

\$\$ADD NG T250017
TYP01 M
DAT01 250103
CLA01 U
RVD01 230124
FRQ01 M121.2000
EXD01 270629
STC01 XT
EMS01 5K00A3E
PWR01 W.02000
STC02 XT
EMS02 6K00A3E
PWR02 W.02000
XSC01 TX
XAL01 SAN ANTONIO
XLA01 292230N
XLG01 0983422W
XAZ01 ND
XCL01 WI 2XUT
XRC01 20170888
RSC01 TX
RAL01 SAN ANTONIO
RLA01 292230N
RLG01 0983422W
ACL01 WI 2XUT
BUR01 FCC
NET01 ELS05
TME01 3
BIN01
DKT01 J1828714
REM01 *RAD,0002,0001NM,B
REM02 *EQT,C,RWC VHF-2100E
REM03 *EQR,C,RWC VHF-2100E
REM04 *FLN,0697-EX-CR-2020
REM05 *FLN,0659-EX-CR-2022
REM06 *AGN,+ THE BOEING COMPANY
REM07 *AGN,+ PWR IS ERP
REM08 *AGN,FLL=000,FLT=001 +TESTING
REM09 *NTS,M018,FAA ,250103,LCARVAJ,NG T250017
NTS01 C089
SUP01 VC-25 AIRCRAFT GROUND EMC TESTING. STOP BUZZERS PHILLIP GONZALES 210-60
SUP02 0-7639 AND JOHN HENTZE JRE 206-369-0339.