



1 Davis Farm Road
Portland, Maine 04103

RECEIVED

DEC 03 2012

Received & Inspected

NOV 26 2012

FCC Mail Room

FCC-Competition Policy Division November 16, 2012

Federal Communications Commission
445 12th Street SW
Washington, DC 20554
Att: Carmell Weathers
Wireline Competition Bureau

Subject: Network Notification No. 65

Short Term Public Notice Under Rule 51.333a
(Less than 6 months notice)

This Notice, pursuant to CFR 47, Subsections 51.325 – 51.335 advises of the following Network change(s) and/or improvement(s) within Telephone Operating Company of Vermont LLC d/b/a FairPoint Communications ("TOCOVT") and the scheduled implementation date.

Vermont Wire Centers:

Burlington Vermont (BURLVTMA),
FairPoint Remote Terminal CLI #1
FairPoint Remote Terminal CLI #2

FairPoint Remote Terminal CLI #3
FairPoint Remote Terminal CLI #4

Burlington Remote Terminal
SBTNVTPZ, SBTNVU0032, SBTNVU0037
SBTNVTIA, SBTNVU0013,
BURLVTU0007, SBTNVU0053
BURLVTU0006, BURLVTRJ
BURLVTU0020, BURLVTRG

Planned Implementation or Retirement Date:

April 2013

Description of Foreseeable Impact: After the planned network changes are implemented, there will be no copper (metallic) loop facilities between FairPoint's Central Office and customer premises in the affected area. Copper (metallic) sub-loop facilities will remain in place between FairPoint's Remote Terminal and customer premises in the affected area.

The following loop types will be transferred to new DLC systems:

2-Wire Analog Voice Grade Loop 4-Wire Analog Voice Grade Loop
2-Wire ISDN Digital Grade Loop 4-Wire 56 kbps Loop
DS1 Loop

Description of Change: The following UNE loop types plus any services not specifically identified that require copper cable for provisioning will no longer be available from FairPoint's Central Office to customer premises in the affected area:

2-Wire ADSL - Compatible Loop 2-Wire HDSL - Compatible Loop
4-Wire HDSL - Compatible Loop 2-Wire IDSL - Compatible Metallic Loop
2-Wire SDSL - Compatible Loop 2-Wire Digital Designed Metallic Loop

Any such UNE xDSL or metallic loops that are in service on the Implementation Date will be disconnected.

Attachment: Certificate of Service

Contact: Mary Groom
802-863-0881
mgroom@fairpoint.com

Barbara Galardo (Regulatory)
207-535-4126
bgalardo@fairpoint.com