



1101 Connecticut Avenue, N.W.
Suite 1200
Washington, D.C. 20036
(202) 248-5150

July 8, 2015

ACCEPTED/FILED

VIA HAND DELIVERY

JUL - 8 2015

Marlene H. Dortch
Secretary
Federal Communications Commission
445 12th Street, S.W.
Washington, D.C. 20554

Federal Communications Commission
Office of the Secretary

Re: Inmarsat Section 25.170 Annual Satellite Report - Erratum

Dear Ms. Dortch:

Inmarsat hereby corrects its 2015 annual report filed pursuant to Section 25.170 of the Commission's rules. 47 C.F.R. § 25.170. The market access authorization for Inmarsat-5 F2 is for the 55.0° W.L. orbital location, and all references in the report to the location of this satellite should have been to 55.0° W.L.

Please contact the undersigned with any questions regarding this matter.

Respectfully submitted,

Christopher J. Murphy
Vice President, Government Affairs

2015 ANNUAL REPORT

2015 Annual Report



1101 Connecticut Avenue, NW
Suite 1200
Washington, DC 20036
202.248.5150

July 1, 2015

VIA HAND DELIVERY

Marlene H. Dortch
Secretary
Federal Communications Commission
445 12th Street, S.W.
Washington, D.C. 20554

ACCEPTED/FILED

JUL - 1 2015

Federal Communications Commission
Office of the Secretary

Re: Inmarsat Section 25.170 Annual Satellite Report

Dear Ms. Dortch:

Inmarsat submits its annual report pursuant to Section 25.170 of the Commission's rules. 47 C.F.R. § 25.170. This report covers the Inmarsat satellites that have been placed on the ISAT List (Inmarsat-3 F2, Inmarsat-3 F3, Inmarsat-3 F4, Inmarsat-4 F1, Inmarsat-4 F2, Inmarsat-4 F3) and as well as the Inmarsat-5 F2 satellite, which has been authorized to serve the United States using Ka-band frequencies.

Please contact the undersigned with any questions regarding this matter.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "C. J. Murphy".

Christopher J. Murphy
Vice President, Government Affairs

REDACTED FOR PUBLIC INSPECTION

INMARSAT
ANNUAL SATELLITE REPORT
AS OF MAY 31, 2015

I. SPACE STATIONS NOT AVAILABLE FOR SERVICE OR NOT PERFORMING TO SPECIFICATIONS

The Commission granted market access for Inmarsat-5 F2 at 55.2° W.L. on March 30, 2015. *See Inmarsat Mobile Networks, Inc.*, Order and Authorization and Declaratory Ruling, 30 FCC Rcd 2770 (2015). This authorization is subject to the milestone schedule set forth in Section 25.164(a) of the Commission's rules. *See id.* ¶ 50; 47 C.F.R. § 25.164(a). The satellite has been launched but has not yet been brought into commercial operation at 55.2° W.L.

REDACTED

REDACTED

II. CONTACT INFORMATION

A. Resolution of Short-Term, Immediate Interference Issues

For emergency situations that require immediate attention:

Kevin Baker
SAS Engineer, Paumalu Hawaii
6211 Glen Circle
Lino Lakes, MN 55014
Email: kevin.baker@inmarsat.com
M: +1-808-469-7104

B. Long-term Engineering and Technical Design Issues

Christopher J. Murphy
Vice President, Government Affairs
1101 Connecticut Avenue, NW
Washington, DC 20036
Email: chris.murphy@inmarsat.com
Telephone: 202-248-5158

III. STATUS OF CONSTRUCTION OF REPLACEMENT SATELLITES

Not applicable.