

The FAA Spectrum Engineering Services has completed the review of your Frequency Coordination Request.

TRK 230599 is assigned an FAA Coordination number NG T230623 that indicates FAA's coordination that may or may not include operational limits/conditions as part of the requirement for FAA concurrence. The FAA Spectrum Engineering Services has provided the following comments:

COMMENTS: NONE

Please note that this concurrence does not constitute authority to transmit. Your authority to transmit must be obtained from the FCC.

Please provide this concurrence notice to the FCC as part of your frequency application, to demonstrate completion of the FAA coordination process. The FAA Coordination number is only valid until 6/1/2024; if you need an extension, please submit an inquiry via WebFCR .

The attached file contains a Card 3 format with all technical and operational parameters; operations are required to be contained within these parameters for the FAA's concurrence to remain valid. If any of these parameters change, the license to transmit shall be re-coordinated with the FAA and updated with the FCC. A document that explains each field of the Card 3 format in plain text is attached.

The following Revision Table outlines key parameters of this coordination:

Attribute	Record Parameter
Serial Number	NG T230623
Frequency	M5040.9475
City	PENDLETON
State	OR
Transmitter Radius	2 NM
Transmitter Latitude	454143.00N
Transmitter Longitude	1185029.00W
Antenna Height	33 Feet
Receiver Latitude	454143.00N
Receiver Longitude	1185029.00W
Antenna Type	PATCH

Best regards,

FAA Spectrum Engineering Services