

Validation Report for 1 created on 05/06/2024 - start time: 11:19:54 - duration: 0min. 8sec. by user DAVEM using version: 9.1.23.5

C:\Users\davem\OneDrive\Documents\2023 MIRA Programs\Shepard Mullin\GLUWA\ITU Filing\CTC-0_RevE_API.mdb

Satellite Name:CTC-0 - Adm.:USA - Orb. Pos.: NGSO Station Type: N

VALIDATION RESULT: 22 Errors Fatal Errors:6 Warnings:16

Beam	E/R	Grp Id	Table	Field	Value	Row	Valerr	Rule	F/W	Ap4 Ref	Error Message
SRX	R	5	e_as_stn	bmwidth	2.2	3	695	4	W	C.10.d.4	Value outside computed allowable range (2.52 - 3.21)
SRX	R	5	e_as_stn	bmwidth	2.2	2	695	4	W	C.10.d.4	Value outside computed allowable range (2.3 - 2.93)
SRX	R	5	e_as_stn	bmwidth	2.2	1	695	4	W	C.10.d.4	Value outside computed allowable range (2.52 - 3.21)
SRXM	R	6	e_as_stn	bmwidth	2	2	695	4	W	C.10.d.4	Value outside computed allowable range (2.52 - 3.21)
STX	E	3	e_as_stn	bmwidth	2	1	695	4	W	C.10.d.4	Value outside computed allowable range (2.52 - 3.21)
STX	E	3	e_as_stn	bmwidth	2.4	4	695	4	W	C.10.d.4	Value outside computed allowable range (2.64 - 3.37)
STX	E	3	e_as_stn	bmwidth	2.2	2	695	4	W	C.10.d.4	Value outside computed allowable range (2.3 - 2.93)
STX	E	3	e_as_stn	bmwidth	2	3	695	4	W	C.10.d.4	Value outside computed allowable range (2.52 - 3.21)
STXM	E	4	e_as_stn	bmwidth	2	2	695	4	W	C.10.d.4	Value outside computed allowable range (2.52 - 3.21)
STXM	E	4	e_as_stn	noise_t	1000	1	693	2	W	C.10.d.6	Invalid value
URX	R	2	e_as_stn	bmwidth	35	1	695	4	W	C.10.d.4	Value outside computed allowable range (22.24 - 28.32)
UTX	E	1	e_as_stn	bmwidth	35	1	695	4	W	C.10.d.4	Value outside computed allowable range (22.24 - 28.32)
UTX	E	1	e_as_stn	noise_t	750	3	693	2	W	C.10.d.6	Invalid value
UTX	E	1	e_as_stn	noise_t	750	2	693	2	W	C.10.d.6	Invalid value
SRX	R	5	grp	op_agcy	999		605	3	F	A.3.a	Value = 999 ; please either request the Bureau to allocate an operating agency symbol first, or enter 999 and provide the details of the operating agency or company in an attachment
SRXM	R	6	grp	freq_max	2010		664	6	W		Frequency band is subject to coordination, please check the details in the Radio Regulations and submit a coordination request as needed
SRXM	R	6	grp	op_agcy	999		605	3	F	A.3.a	Value = 999 ; please either request the Bureau to allocate an operating agency symbol first, or enter 999 and provide the details of the operating agency or company in an attachment
STX	E	3	grp	op_agcy	999		605	3	F	A.3.a	Value = 999 ; please either request the Bureau to allocate an operating agency symbol first, or enter 999 and provide the details of the operating agency or company in an attachment
STXM	E	4	grp	freq_max	2200		664	6	W		Frequency band is subject to coordination, please check the details in the Radio Regulations and submit a coordination request as needed
STXM	E	4	grp	op_agcy	999		605	3	F	A.3.a	Value = 999 ; please either request the Bureau to allocate an operating agency symbol first, or enter 999 and provide the details of the operating agency or company in an attachment

Beam	E/R	Grp Id	Table	Field	Value	Row	Valerr	Rule	F/W	Ap4 Ref	Error Message
URX	R	2	grp	op_agcy	999		605	3	F	A.3.a	Value = 999 ; please either request the Bureau to allocate an operating agency symbol first, or enter 999 and provide the details of the operating agency or company in an attachment
UTX	E	1	grp	op_agcy	999		605	3	F	A.3.a	Value = 999 ; please either request the Bureau to allocate an operating agency symbol first, or enter 999 and provide the details of the operating agency or company in an attachment